

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	
1	5900 SELINSKY	US BROWNFIELDS	1016349246
Target	5900 SELINSKY	FINDS	N/A
Property	HOUSTON, TX 77048		

Actual:
41 ft.

US BROWNFIELDS:

Recipient name:	Houston, City of
Grant type:	Assessment
Property name:	5900 SELINSKY
Property #:	0450780000085
Parcel size:	11.93
Property Description:	This 25-building complex was built in 1974. It has vacant land on three sides, but illegal dumping is at the boundary on each of those sides. (PPF - Crystal Springs Apartments, 11/2/06)
Latitude:	29.637419
Longitude:	-95.327589
HCM label:	Interpolation-Satellite
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	World Geodetic System of 1984
ACRES property ID:	40209
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	3226.69
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	H
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	97699601
Ownership entity:	Private
Current owner:	Meadow Green Housing Corp.
Did owner change:	N
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controlled substance found:	Not reported
Controlled substance cleaned:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

5900 SELINSKY (Continued)

1016349246

Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	11.93
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	11.93
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

5900 SELINSKY (Continued)

1016349246

No contaminant found: Y
Pesticides contaminant found: Not reported
Selenium contaminant found: Not reported
SVOCs contaminant found: Not reported
Unknown contaminant found: Not reported
Future Use: Multistory Not reported
Media affected Bluiding Material: Not reported
Media affected indoor air: Not reported
Building material media cleaned up: Not reported
Indoor air media cleaned up: Not reported
Unknown media cleaned up: Not reported
Past Use: Multistory Not reported

FINDS:

Registry ID: 110038756593

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES)
is an federal online database for Brownfields Grantees to
electronically submit data directly to EPA.

2
NE
1/4-1/2
0.261 mi.
1378 ft.

SELINSKY
6101 SELINSKY RD
HOUSTON, TX 77048

SWF/LF **S109701768**
SWRCY **N/A**
Financial Assurance

Relative:
Higher

Actual:
41 ft.

SWF/LF:
Region: 12
Permit Number: 100221
Facility Status: ACTIVE
Facility Type: 5RR
Permit Status: ISSUED
Status Date: 07/14/2009
Mailing Address: Not reported
Client Name: Not reported
Client Address: Not reported
Client Telephone: N/A
Business Type: BUSINESS
Area Served: HARRIS
Estimated Closure Date: Not reported
Permit Acreage: NA
Permit Start: 05/01/2009
Permit End: 07/14/2009
Polution Served: Not reported
Tons per Day: NA
Yards per Day: NA
Application: NEW APPLICATION
Lat/Long: 29.64 / -95.32

SWRCY:

Facility Type: Recycling and Recovery Facility
Program: MSW
Additional Id: 100221
Legal Status: ISSUED - Start 05/01/2009